## Sikka Kaamya Project

## Progress Report for the period 24-03-2025 to 30-03-2025

Tower	Towar						
Name	Tower Photo	Item	Progress of work				
DIAMOND		RMC/Steel	12th floor columns and shear wall - Aluminium shuttering in progress				
		Paint	Internal paint to start this week				
		Tiling	1st floor completed				
		Plumbing	1st floor completed				
		Electrical	Yet to start				
		M.S. Railings	Yet to start				
		Internal Plaster	5th floor in progress				
		External Plaster	N/A				
		Fire Fighting	Yet to start				
RUBY		RMC	Structure Work Completed				
		Paint	Intenal putty work completed, external primer done 60%				
		Tiling	Floor Tiling at 20th floor in progress				
		Plumbing	Internal water supply and drainage work completed				
		Electrical	Conduit work completed, wiring work yet to start				
		M.S. Railings	Balcony railing completed and staircase railing in progress				
		Internal Plaster	Completed				
		External Plaster	94% completed				
		Fire Fighting	Internal sprinkler system piping completed				
		RMC	Structure Work Completed				
OPAL		Paint	Intenal putty work completed, external primer done 55%				
		Tiling	Wall Tiling at 19th floor completed				
		Plumbing	Internal water supply and drainage work completed				
		Electrical	Conduit work completed, wiring work yet to start				
		M.S. Railings	Balcony railing completed and staircase railing in progress				
		Internal Plaster	Completed				
		External Plaster	88% completed				
		Plaster					

	The state of the s	Fire Fighting	Internal sprinkler system piping completed
JADE		Brickwork / RMC	Lift shaft brickwork in progress
		Paint	Intenal putty work completed, external primer done 50%
		Tiling	Wall Tiles for toilets at 19th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Completed -90%
		External Plaster	82% completed, balance work in progress
		Fire Fighting	Internal sprinkler system piping in progress
AMBER	The second of th		Structure Work Completed
		Paint	Internal putty work completed, external primer done 62%
		Tiling / Granite work	Floor tile at 14th floor in progress
		Plumbing	Internal water supply and drainage work completed
		Electrical	Conduit work completed, wiring work yet to start
		M.S. Railings	Balcony railing completed and staircase railing in progress
		Internal Plaster	Lift lobby internal plaster - 21st floor
		External Plaster	92% completed
		Fire Fighting	Internal sprinkler system piping completed
		RMC	Structure Work Completed
SAPPHIRE		Paint	Intenal putty work completed, external painting done 80%
		Tiling	Lift Wall Tile Cladding at 18th floor completed
		Plumbing	Completed
		Electrical	Conduit work completed, wiring work in progress
		M.S. Railings	Completed
		Internal Plaster	Completed
		External Plaster	Completed
		Fire Fighting	Completed

PEARL		RMC	Structure Work Completed
		Paint	Completed, final coat balance
		Tiling	Completed
		Plumbing	Completed
		Electrical	Completed
		M.S. Railings	Completed
		Internal Plaster	Completed
		External Plaster	Completed
		Fire Fighting	Completed
EMERALD		RMC/Steel	4th floor shear walls - R/F work work in progress
		Paint	Yet to start
		Tiling	Yet to start
		Plumbing	Yet to start
		Electrical	Yet to start
		M.S. Railings	Yet to start
		Internal Plaster	Yet to start
		External Plaster	N/A
		Fire Fighting	Yet to start