



Sikka Kimaantra Greens

Progress Report For 18.02.25 to 24.02.25

Tower	Photo	Work Done i.e.
	 A photograph showing two construction workers in safety vests and hard hats working on a concrete floor. One worker is standing and holding a concrete block, while the other is crouching and using a tool to lay a block. There is a pile of concrete blocks and a bucket of cement on the floor.	Block Work
	 A photograph showing a construction worker in a red safety vest and yellow hard hat laying concrete blocks on a floor. The worker is bending over, placing a block. There are several concrete blocks scattered on the floor, and a window is visible in the background.	



NTA



Any Other Work





RCC Work

Tower Name

Tower Photo

Work Done i.e.



Club



Any Other Work





Tower Name

Tower Photo

Work Done i.e.



Villa

Any Other Work



Tower Name

Tower Photo

Work Done i.e.

Tower 01,02



Other Work